









Group:	AVi150 Series Alternators	Notes:
Form:	SP4017_AVi150_Series	Service parts listing. (AVi150 Series)
Date:	August 14 , 2014 (Rev: 1)	
File:	Service parts list section	


Component View	Front housing	Rear housing	Rotor	Stator	Rectifier kit	Regulator kit	Front bearing kit
							
Part number	1	2	3	4	5	6	7
AVi150P1103HP	6530-63	6530-74	6530-27	6530-88	6530-170	6530-171A	6530-172
AVi150S1104HP	6530-47	6530-101	6530-27	6530-88	6530-252	6530-254	6530-172
AVi150S1108HP	6530-143	6530-146	6530-27	6530-88	6530-252	6530-254A	6530-172
AVi150S1109HP	6530-47	6530-101	6530-27	6530-88	6530-252	6530-254	6530-172
AVi150S1112HP	6530-143	6530-146	6530-27	6530-88	6530-252	6530-254A	6530-172

Component View	Rear bearing kit	Slip ring cover kit	Rear cover kit	Pulley kit	Through bolt kit	Notes
						
Part number	8	9	10	11	12	
AVi150P1103HP	6530-173	6530-174	6530-175	6530-176	6530-177	Pulley included
AVi150S1104HP	6530-173	6530-174	6530-175B	6530-253A	6530-177	Pulley included
AVi150S1108HP	6530-173	6530-174	6530-175A	6530-253	6530-177	Pulley included
AVi150S1109HP	6530-173	6530-174	6530-175A	6530-253	6530-177	Pulley included
AVi150S1112HP	6530-173	6530-174	6530-175B	6530-253	6530-177	Pulley included

Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Group:	AVi150 Series Alternators	Notes:
Form:	SP4017_AVi150_Series	Service parts listing. (AVi150 Series)
Date:	August 14 , 2014 (Rev: 1)	
File:	Service parts list section	

EXPLODED VIEW & KIT IDENTIFICATION



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:




ALTERNADOR AVI150 SCANIA 24V-190A EQ. ORIGINAL

- Producto nuevo equipo Original
- 24V / 190A
- Equipo Original Scania modelo 2013/

Prestolite se complace en anunciar el lanzamiento en Argentina de la serie de alternadores para Camiones y Buses Scania.

Para mas Informacion contactese con su distribuidor mas cercano.



PART NO.	V	A	ER / IR	Rot'n	Shaft Ø	Pulley	APPLICATION	REFERENCES *
AVI150P2114HP	24V	190A	ER	CW	17mm	10pV, 71mm	SCANIA R-SERIES TRUCK SCANIA BUS	2448165, 2853478, 2905970, 2572595, 2920858, 570718 AVI150P2101HP, AVI150P2116HP
 Available March 2021								
AVI150P2124HP	24V	190A	ER	CW	17mm	OAP 10pV, 71mm	SCANIA BUS	2470900, 2573973, 2905976, 2911438, 570678, 2853488 AVI150P2104HP, AVI150P2115HP
 Available Q2 2021								
AVI150P2125HP	24V	190A	ER	CW	17mm	10pV, 81mm	SCANIA TRUCK	2479047, 2572596, 2905972, 2920880, 570719, 2853479 AVI150P2102HP, AVI150P2117HP
 Available Q2 2021								

Manufacturer's numbers are for reference only. *

